





ACCESSORY WIRING



ONBOARD TEMPERATURE
SENSOR - TRIP POINT 45°F
* WPM.XT OPTION BELOW


POWER SUPPLY
CONNECTION
WATER PROBE
CONNECTION
WATER PROBE
CONNECTION
AUX CONNECTION



ENCLOSURE: ABS
POWER REQUIREMENTS: 2 AAA ALKALINE BATTERIES
MOUNTING: SCREWS AND ANCHORS PROVIDED


OPTIONAL ACCESSORIES

**STANDARD PRO SENSOR
(WPSC)**




10'

**AC ADAPTER
(ACA100)**




**ROPE SENSOR
(WROPE6)**




6'

**PRESSURE SWITCH
(WPRS095)
FACTORY SET AT 95 PSI
FIELD ADJUSTABLE**




10'

**SPLITTER
(WSPLIT)**



**EXTENSION
(WEXT6)**



6'

OPTION: WPM.XT HUB W/ TEMPERATURE SENSOR DISABLED

**UNCONTROLLED
DRAWING**

THIS PRINT IS THE PROPERTY
OF DYNAQUIP CONTROLS AND
SHALL NOT BE COPIED,
REPRODUCED, LOANED,
OR DISPOSED OF DIRECTLY
OR INDIRECTLY, NOR USED
FOR ANY PURPOSE OTHER THAN
THAT FOR WHICH IT IS
SPECIFICALLY FURNISHED
EXCEPT BY WRITTEN
PERMISSION OF
DYNAQUIP CONTROLS.

NO. **WPM / WPM.XT** FILE NO. **SUB472**

TITLE **WATERCOP PRO
MULTISENSE HUB**

DR MJP	DATE 11-17-21	CHKD	DATE	ENGR	DATE
-----------	------------------	------	------	------	------

